Declassified in	Part - Sanitized	Central Intelli		:: CIA-RDP80-00926A004300030	016-6 HUM
		INFORMATIO	N REPOI	RT CD NO.	
COUNTRY	Hungary			DATE DISTR. 8 Oct 51	
SUBJECT	The Nitrogen (Peti Nitrog	Works at Petfurdo, en Muvek N V)	Hungary	NO. OF PAGES 2	
PLACE ACQUIRED				NO. OF ENCLS. 2	je <b>5</b>
DATE ACQUIRED				( <b>B)</b> SUPPLEMENT TO REPORT NO.	50X1-HUM
DATE OF (					30X1-HUIVI
OF THE UNITED STATULES. C., 31 AND 32. OF ITS CONTENTS IN	TAINS INFORMATION AFFECTI TES WITHIN THE MEANING O AS AMENDED. ITS TRANSIC ANY MANNER TO AN UNAUI REPRODUCTION OF THIS FOR	F THE ESPIONAGE ACT 50 SSION OR THE REVELATION THORIZED PERSON IS PRO-	THIS	IS UNEVALUATED INFORMATION	50X1-HUM
1.	The Nitrogen	Works at Petfurdo, wing persons:	Hungary Zsee	enclosed sketch/ is operate	d
	(a) Gene	ral Manager: Steph	en Vajda.		
	(b) Chie Comm	f of Management; Cunist Party.	harles Angyal	, machinist, member of the	


- (c) Manager: Rudolf Jenei, member of the Communist Party and former chauffeur.
- (d) Secretary to the Party: Alexander Domjan.
- 2. The number of employees is 4,500; 150 engineers and technical personnel; 150 office clerks; and 1,000 specially trained workers. The workmen live in the neighboring towns and villages of Veszprem, Berhida, Osi, Osku, Inota, and Varpalota.
- 3. The oil-acids-sulphur works and synthetic works operate in three shifts. All others work in one shift The plant accomplished a 125% fulfillment of the Five Year Plan in 1950.
- 4. Underground gas (benzine) reservoirs are in the forest of Cseri, southwest of Varpalota. Each tank contains 1,000 cu m . A pipe line was laid from there to the plant at Pet.
- 5. The Fire Brigade numbers 150 men, with the most up-to-date equipment, who also do the security service in the plant.

- end -

(A): Sketch of the Nitrogen works at Petfurdo, Hungary

(B): Legend to Enclosure (A)

CLASSIFICATION SECRET/US OFFICIALS ONLY STATE NSRB DISTRIBUTION ARMY ORR EV



ENCLOSURE (B)

00-B-39426

LEGEND TO THE SKETCH OF THE NITROGEN WORKS AT PETFURDO, HUNGARY

1. Management

- 2. Living quarters of the employees3. Workmen's living quarters

4. Garages

5. Stores (marketing) 6. Management Committee

Entrance guard

8. Baths, and Laundry

- 9. First Aid Station, Medical Ambulance
- 10. Synthetic plant, produces basic material for the Nitro-chemical Works at Fuzfo, for the production of gunpowder, Manager: Chief Engineer Karl Hidegkuti, an expert.

Phosphorus Plant, produces industrial phosphorus from Italion raw phosphorus. Manager: Chief Engineer Ponner, is not a Communist

- 12. Benzine Plant, refines the crude oil received from Lispe through a pipe line for making benzine gas, paraffin oil, and gas oil. Oil for heating is shipped from here to the Hungarian State Railways. One thousand tons of crude oil are being refined here per month. Fuel for planes and medical benzine is also being produced here.
- 13. These are 13-meter-high towers, in which the crude oil is being heated. Production results: 33% benzine, 30% paraffin oil, and 20% gas oil, the rest is fuel oil.

14. 5-meter-high towers, for fuel and reservoirs, 10 pieces

- 15. Filling stations and reservoirs, with pipe line to the main reservoirs, the railroad cars are being filled here
- Benzine laboratories. On the ground floor technical bureaus. Strictly guarded, and closed off by a fence. Leader, Engineer Janeso, is not a Communist.

17. Fire Brigade, very up-to-date equipment.

- 18. Apprentice School. Work shops with modern equipment on the main floor, for repairs needed at the plant. Leader, Engineer Koloman Pettko.
- 19. Gas works produces coke needed by the plant, (coal comes from Varpalota) only for the use of the factory, such as central heating, power works, steam boiler heating etc. Leader Carl Misky, engineer, former Nazi, now a Communist.
- 20. Power plant. Oil and coke heating. Capacity 22,000 KW. Supplies power for the plant am also Petfurde, Varpalota. Leader, Engineer Charles Ratz, a Communist.

21. Stores (material)

- 22. Controller of internal revenues. (fiscal office)
- 23, 24, &25. Workshops, (forge, locksmiths, and carpenter). Up-to-date equipment. Leader Julius Geiger, former Nazi, now a Communist.

26. Cable railway to Varpalota for transport of coal.

- 27. Acids production with two storing towers. Phosphoric acids production for industrial purposes, and also for the Nitre-chemical Works at Fuzfo. Acids for export to the USSR are also produced here.
- Salt works of Pet. Artificial fertilizer production. The phosphate needed here is imported from the USSR. The leader Charles Lengyel, is not a Communist.
- 29. Offices of the above-mentioned Artificial Fertilizer Plant.

30. Stores for artificial fertilizer.

- 31. Main laboratories for experiments, analyses, control of productions, research, explesives. Leader, Engineer Michael Kenyeres, works in closest cooperation with the Budapest Polytechnicum, Chemical Section
- 32. Acids reservoir.